NVL Laboratories, Inc. 4708 Aurora Ave N, Seattle, WA 98103

Analysis Report Polychlorinated Biphenyls (PCBs)

p 206.547.0100 | f 206.634.1936 | www.nvllabs.com



Client: NVL Field Services Division

Address: 4708 Aurora Ave. N.

Seattle, WA 98103

NVL Batch #: 1418022.00

Method No.: EPA 8082

Client Project #: 2012-494

Date Received: 10/9/2014

Matrix: Bulk

Samples Received: 2

Samples Analyzed: 2

Attention:	Mr. Marcus Gladden
Project Location:	3100 Airport Way South Seattle,WA 98134

Lab Sample ID:	14128826	14128827
Client Sample ID:	10914-BULK-1	10914-BULK-2
Sample Description:	Blue Paint, Bldg. 13 SW	Sandstone, Bldg. 10 W
Sample Weight (g)	1.0403	2.0156
PCB Type	mg/Kg(ppm)	mg/Kg(ppm)
Aroclor 1016	ND	ND
Aroclor 1221	ND	ND
Aroclor 1232	ND	ND
Aroclor 1242	ND	ND
Aroclor 1248	ND	ND
Aroclor 1254	100.00	2.8
Aroclor 1260	29.00	1.5
Total: PCB Concentration	129.0	4.3
Reporting Limit (RL)	19.0	1.0

Remarks: mg/Kg = Milligrams per kilogram

ND = None Detected (less than RL)

ppm = Parts per million by weight

<RL = Below the reporting limit of instrument

Sampled by: Client

Analyzed by: Shalini Patel
Reviewed by: Nick Ly

Date:10/10/2014 **Date:**10/10/2014

4

Nick Ly, Technical Director

Preparation and analysis of these samples were conducted in accordance with published test methods. Unless stated otherwise, the condition of all samples was acceptable at time of receipt. Reported sample results are based on dry weight and method QC results are acceptable unless stated otherwise. If samples were not collected by NVL personnel, then the accuracy of the results is limited by the methodology and acuity of the sample collector. This report shall not be reproduced except in full, without written approval of NVL Laboratories, Inc.. Responsibility for interpretation of the reported data rests with the client.

NVL Laboratories, Inc.

Results report to

CHAIN of CUSTODY



1418022 4708 Aurora Ave N. Seattle, WA 98103 SAMPLE LOG p 206.547.0100 | f 206.634.1936 | www.nvllabs.com NVL Batch Number Client NVL Laboratories Inc Client Job Number 2012-494 Street 4708 Aurora Ave N **Total Samples** Seattle, WA 98103 Turn Around Time □ 10 6 Hrs Project Manager Munaf Khan 2 Hrs Project Location 3100 Airport Way South Seattle, WA 98134 Please call for TAT less than 24 Hrs **Email address** Phone: (206) 447-0263 Fax: (206) 447-0299 TEM (NIOSH 7402) TEM (AHERA) TEM (EPA Level II) Asbestos Air PCM (NIOSH 7400) PLM (EPA Gravimetry) TEM BULK Asbestos Bulk PLM (EPA/600/R-93/116) PLM (EPA Point Count) ☐ Mold/Fungus Mold Air Mold Bulk Rotometer Calibration Other Metals Matrix **RCRA Metals** B IIA Det. Limit METALS All 3 Soil Air Filter Arsenic (As) Chromium (C Total Metals ☐ FAA (ppm) Copper (Cu) Paint Chips in % Lead (Pb) Drinking water Barium (Ba) TCLP ☐ ICP (ppm) Nickel (Ni) GFAA (ppb) Dust/wipe (Area) Paint Chips in cr ☐ Cadmium (Cd) ☐ Mercury (Hg) Cr 6 Zinc (Zn) Other Types ✓ Other (Specify) Nuisance Dust Fiberglass Silica of Analysis Respirable Dust Severe damage (spillage) **Condition of Package:** Good Damaged (no spillage) A/R Client Sample Number | Comments Seq.# Lab ID BLDG 13 SW BLUE PAINT 10914 - BULK - 1 2 SANDSTONE BLOG 10 3 4 5 6 7 8 9 10 11 12 13 14 15 Time Print Below Sian Below Company MARIUS (GLADATE) NYL 11:30 ABS Sampled by 14:15 Relinquished by Received by Analyzed by Results Called by Results Faxed by

Special Instructions: Unless requested in writing, all samples will be disposed of two (2) weeks after analysis.